


p1, row1, col2


Cut to clear servo






p1, row1, col3

p1, row1, col4



p1, row2, col1

Stiffener (4.5 x 1mm carbon strips)




p1, row2, col2

Cut to fit motor

[illegible]


p1, row2, col4

Cut to fit servo







p1, row3, col1



p1, row3, col2







p1, row3, col3


Wing spar posit

p1, row3, col4

Cut to fit servo





Ply motor mount



p1, row4, col2

Cut to clear servo





p1, row4, col3

p1, row4, col4

